



## TECHNICAL SERVICE BULLETIN

**Technical Service Bulletin Number-TSB0010 – Step-N-Lock Maintenance**

**Date – 08/02/2019**

**Item, Unit or Assembly Affected – Step-N-Lock**

**Unit(s) Affected – All**

**Reason for Bulletin –** The pivot joint at the CAM bolt may become less binding over time and repeated use. As a result, the step-bar may fall to the “locked” position under its own weight, making the Step-N-Lock seat less convenient to relocate.

### Tools Needed –

- ¼” Allen key / Ratchet + ¼” Allen bit
- 9/16” Wrench

**Action Required –** Snug the indicated nut and bolt to prevent the step-bar from falling under its own weight. The step-bar should be easily moved, but not loose.



**Safety Issue? - No.**