



## TECHNICAL SERVICE BULLETIN

**Technical Service Bulletin Number-TSB0004 – Freedman Seat Handle**

**Date – 10/2/2018**

**Item, Unit or Assembly Affected – Freedman GO-ES Double Fold Seats specific to OPWDD or NYS DOT Upfits**

**Serial Number(s) Affected-N/A see above**

**Reason for Bulletin- Small Folding Handle on some seats may be stripped or break. This is manufacturers defect and will be replaced upon request if customer is experiencing a problem.**

**Action Required - Contact Mary ([mary@abilitrax.com](mailto:mary@abilitrax.com)) for replacement handles and to arrange repair.**

**Handle**



**Safety Issue? This is not a safety issue or concern**